NO NEED TO SET ZERO BEFORE USE

4908-100

- No need to set zero before use
- With mounting holes (for M5 screws)

Part No.	Length	Sensitivity
4908-100	4"	.0012in/ft (=0.0057°)



