


## SHANK TAPER INSPECTION INSTRUMENTS



gauge master (optional)

- Check the taper of BT shank
- Supplied with dial indicators



check:

d<sub>1</sub>: large taper diameter

d<sub>2</sub>: small taper diameter

L: straightness of the taper

a: relationship of the flange to the taper

### SPECIFICATION

Part No.	4773-30-U	4773-40-U	4773-50-U
Taper	BT30	BT40	BT50
Repeatability	.00005"	.00005"	.00005"

### OPTIONAL ACCESSORY

Gauge master for 4773-30-U	4773-S1
Gauge master for 4773-40-U	4773-S2
Gauge master for 4773-50-U	4773-S3