

## WEIGHING SCALES (HIGH PRECISION)


- LCD display, with backlight
- Zero-setting, subtracting tare value
- Overload alarm
- Automatic power off



printer (optional)



8001-6



### SPECIFICATION

Part No.	8001-6	8001-15	8001-30
Maximum weighing	12lb/6kg	30lb/15kg	60lb/30kg
Minimum weighing	.0090lb/4g	.022lb/10g	.044lb/20g
Resolution (d)	.0005lb/0.2g	.001lb/0.5g	.002lb/1g
Accuracy (m is load)	m≤2.2lb: ±.0025lb 2.2lb<m≤8.8lb: ±.0005lb m>8.8lb: ±.0075lb	m≤5.5lb: ±.005lb 5.5lb<m≤22.0lb: ±.01lb m>22.0lb: ±.015lb	m≤11.0lb: ±.01lb 11.0lb<m≤44.0lb: ±.02lb m>44.0lb: ±.03lb
Units	kg, lb		
Output	no		
Operating temperature	14~104°F		
Power	rechargeable battery (6V/3.2Ah), power adapter (12V/500mA)		
Dimensions of pan	10.354×8.031"		

### SPECIFICATION

Part No.	8001-6D	8001-15D	8001-30D
Maximum weighing	6kg	15kg	30kg
Minimum weighing	4g	10g	20g
Resolution (d)	0.2g	0.5g	1g
Accuracy (m is load)	m≤2.2lb: ±.0025lb 2.2lb<m≤8.8lb: ±.0005lb m>8.8lb: ±.0075lb	m≤5.5lb: ±.005lb 5.5lb<m≤22.0lb: ±.01lb m>22.0lb: ±.015lb	m≤11.0lb: ±.01lb 11.0lb<m≤44.0lb: ±.02lb m>44.0lb: ±.03lb
Units	kg		
Output	RS232		
Operating temperature	14~104°F		
Power	rechargeable battery (6V/3.2Ah), power adapter (12V/500mA)		
Dimensions of pan	10.354×8.031"		

### OPTIONAL ACCESSORY (for scales with RS232)

Printer	8001-PRINTER
---------	--------------