

## ELECTRONIC BALANCES

TOUCH  
SCREEN

DATA  
OUTPUT

- Electromagnetic balanced sensor
- Subtracting tare value, accumulation, percentage display
- Zero-setting, weighing, counting, animal scale
- 4.3-inch touch color screen
- Calibration method: external calibration
- Unit: g, ct, oz, mg
- With a hook at the bottom
- Data output



printer (optional)

horizontal bubble



### OPTIONAL ACCESSORY

|             |              |
|-------------|--------------|
| RS232 cable | 8315-CABLE*  |
| Printer     | 8303-PRINTER |

\* Used to connect with computers

### SPECIFICATION

| Code                      | 8315-2000        | 8315-3000   | 8315-5000   | 8315-6000    |
|---------------------------|------------------|-------------|-------------|--------------|
| Maximum weighing          | 2kg/10000ct      | 3kg/15000ct | 5kg/25000ct | 6kg/30000ct  |
| Minimum weighing          | 0.5g/2.5ct       | 0.5g/2.5ct  | 0.5g/2.5ct  | 0.5g/2.5ct   |
| Resolution (d)            | 0.01g/.05ct      | 0.01g/.05ct | 0.01g/.05ct | 0.01g/.05ct  |
| Verification interval (e) | 0.1g/.5ct        | 0.1g/.5ct   | 0.1g/.5ct   | 0.1g/.5ct    |
| Accuracy                  | ±0.05g/.25ct     |             | ±0.1g/.5ct  | ±0.15g/.75ct |
| Weighing pan size         | 6.89×6.89"       |             |             |              |
| Output                    | RS232            |             |             |              |
| Operation temperature     | 32~104°F         |             |             |              |
| Operation humidity        | ≤80% RH          |             |             |              |
| Power supply              | 110V, 50/60Hz    |             |             |              |
| Dimension (L×W×H)         | 13.19×8.46×4.13" |             |             |              |

