

ATTENTION:
LOW ACCURACY

- Zero-setting, subtracting tare value
- Automatic power off
- LCD display, with backlight
- Unit: kg
- Overload indication

SPECIFICATION

Maximum weighing	40kg
Minimum weighing	1kg
Resolution (d)	50g
Accuracy	±50g
Operation temperature	14~113°F
Operation humidity	30%~90%RH
Limited load	50kg
Power supply	2×AAA batteries



8604-40

PORTABLE CRANE SCALE PART NO. 8604-40



built-in measuring tape (included)