


- Counting, animal scale, accumulation
- Zero-setting, weighing, subtracting tare value
- Upper and lower limit alarms: quantity, weight
- Resistant rubber with cloverleaf handle-bar
- LCD display, with backlight
- Overload alarm, automatic power off
- Li-ion battery power supply, for 24h continuous working
- Data output
- Unit: kg, lb, g, oz



8802-300

[illegible]