



# CENTERING INDICATOR



2385-3

- Provides quick and accurate centering in boring and milling set-up
- Maximum speed is recommended not to exceed 800RPM

**Part No.**  
**2385-3**

Feeler	Measuring diameter	Accuracy
P1	0-2.362" DIA	.00060"
P2	0-6.299" DIA	.00080"
P3	0-9.843" DIA	.00120"
P4	.126-3.150" DIA	.00060"
P5	.126-7.087" DIA	.00076"
P6	.126-11.024" DIA	.00120"
P7	0- .110" DIA	.00060"

