


GROOVE MICROMETERS




3287-1B


- Graduation .001"
- Measure width of grooves inside bores
- Non-rotating spindle
- Two graduations for inside and outside measurement
- Two-directional ratchet stop




measure width of groove



measure position of groove



measure width of keyway



Part No.	Range (outside A)	Range (inside B)	Accuracy	L	D	D1	D2
3287-1B	0-1"	.06-1.05"	.00039"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-2B	1-2"	1.05-2.05"	.00039"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-3B	2-3"	2.05-3.05"	.00039"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-4B	3-4"	3.05-4.05"	.00039"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-5B	4-5"	4.05-5.05"	.00059"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-6B	5-6"	5.05-6.05"	.00059"	4.724"	.512" DIA	.256" DIA	.394" DIA
3287-1AB	0-1"	.06-1.05"	.00039"	3.543"	.256" DIA	.118" DIA	.197" DIA

***3287-1AB** does not have sleeve