
CENTER GAGES



check the angle of screw cutting tools

machine tools

workpiece

set the position of screw cutting tools

check the angle of screw thread

check the angle of screw thread

check the screw thread pitch

- To check and set screw cutting tools, and check the angle and pitch of screw thread
- Angle accuracy: ±30min.
- Made of stainless steel

Part No.	Thread type	Angle (α)	Graduation
4810-602	UNIFIED 60°	60°	14ths and 20ths on front side, 24ths and 32ths on back side
4810-601	METRIC 60°	60°	0.5mm and 1mm
4810-55	WHITWORTH 55°	55°	14ths and 20ths on front side, 24ths and 32ths on back side