

NO NEED TO SET
ZERO BEFORE USE

LEVEL BUBBLES




4955-3




4955-4




4955-5



4955-3



4955-4



4955-5

- No need to set zero before use

Part No.	Range	Graduation	Accuracy	Working temperature	Base diameter(ØD)	Base type
4955-3	0-3°	1°	±0.2°	-4°F~122°F	1.181"DIA	Stainless steel, without mouting hole
4955-4	0-4°	1°	±0.2°	-4°F~104°F	3.543"DIA	Aluminum alloy, with mouting holes
4955-5	0-5°	2°	±0.4°	-4°F~122°F	3.150"DIA	Aluminum alloy, with mouting holes